

Work Order ID 63212

Monday, October 25, 2010 12:34:31 PM

Page 1

Item ID: D212-725-1-079F

Accept

Setup Start

Revision ID:

Stop

Item Name: Gusset

Start Date: 10/25/2010 Start Qty: 4.00

Cust Item ID:

Required Date: 10/29/2010 Req'd Qty: 4.00

Customer:

Reference:

Approvals:

Process Plan: MDate: 10-10-25

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D212-725-1	B								
100		0.00							
									
Waterjet	Memo	0.00							
FLOW CNC Waterjet	1-Cut as per Dwg								
2024.040	Dwg Rev: <u>B</u>								
	Prog Rev: <u>JS</u>								
	2-Deburr if necessary								
110	QC2- Inspect parts off machine FAI/FAIB	0.00							
									
QC	Memo	0.00							
Quality Control									

KB10-10-27

(4)

KB10-10-27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 63212

Monday, October 25, 2010 12:34:31 PM

Page 2

Item ID: D212-725-1-079F

Accept

Setup Start

Revision ID:

Stop

Item Name: Gusset

Start Date: 10/25/2010 Start Qty: 4.00

Cust Item ID:

Required Date: 10/29/2010 Req'd Qty: 4.00

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

QC8- Inspect parts - second check

0.00



QC

Memo

0.00

Quality Control

S 10/10/27

(4)

130

Identify as per dwg & Stock Location: _____

0.00



Packaging

Memo

0.00

Packaging

FLAT PATTERN ONLY

P/d 10/27 (4)

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/10/27

C2 10/10/27

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 1

Monday, October 25, 2010 12:34:35 PM

Work Order ID: 63212



Parent Item: D212-725-1-079F



Parent Item Name: Gusset

Start Date: 10/25/2010

Required Date: 10/29/2010

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:A 10.07.19 new issue DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

M2024T3S.040		Purchased	No			100	sf	321.7400	0.1089	0.458526			
--------------	--	-----------	----	--	--	-----	----	----------	--------	----------	--	--	--



1810-10-27

2024-T3 .040 sheet

Location

Loc Qty

Loc Code

MAT

84.2

114415

84.2

114415

MAT22

237.54

110305

21.93

111786

13.76

112291

28.25

112331

52

113162

121.6

④

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries


D212-725-1-079F

☒ **First Article** ☐ **Prototype**

Measured by:	RB	Audited by:	S	Prototype Approval:	N/A
Date:	10-10-27	Date:	10/10/27	Date:	N/A



H:\FORMS\Quality Assurance\approved QA\FAI revD

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *63212*
2110-10-25




D212-725-1-077F FLAT PATTERN


**D212-725-1-077 GUSSET (SHOWN)
D212-725-1-078 OPPOSITE
(MAKE FROM D212-725-1-077F FLAT PATTERN)**



**D212-725-1-079 GUSSET (SHOWN)
D212-725-1-080 OPPOSITE
(MAKE FROM D212-725-1-079F FLAT PATTERN)**



D212-725-1-079F FLAT PATTERN



RELEASED
2009-10-8

NOTES:

- 1) MATERIAL: 2024-T3 SHEET 0.040 THICK PER QQ-A-250/4 OR AMS 4037 (REF. DART SPEC. M2024T3S.040)
- 2) FINISH: ACID ETCH, ALODINE 1200 OR 1201 PER MIL-C-5541 AND/OR PRIME & PAINT PER AIRCRAFT MAINTENANCE MANUAL
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.010
- 6) IDENTIFY WITH DART P/N USING FINE POINT PERMANENT INK MARKER

B	07.05.11	NO CHANGE
A	08.12.08	NEW ISSUE
DESIGN RF	DRAWN BY RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED DS	APPROVED <i>[Signature]</i>	DRAWING NO. D212-725-1
DATE 07.05.11	TITLE 212S DETAIL PARTS	REV. B SHEET 30 OF 44 SCALE 1:2
COPYRIGHT © 2006 BY DART AEROSPACE LTD. THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries